

PS4 HDMI Socket repair (70 GBP)



Location Yorkshire and the Humber, South Yorkshire https://www.freeadsz.co.uk/x-252645-z



A common issue with the PS4, they are flimsy and easily damaged. We only us the V2 socket which is a modified version of the original, it is a better design and is a lot less prone to

					-	1	1		T
PS4 HDMI Socket repair https://www.freeadsz.co.uk/x-2526 45-z									