

2 x numark ndx 900 cd decks (1 faulty) plus 1 Numark IM09 mixer. (300 GBP)



Location **East of England, Hertfordshire**
<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks plus 1 Numark IM09 mixer. Crossfader crackly just needs changing. Both decks in good condition. 1 of the decks needs a new cd drive as only whiring sounds are happening. Cost of cd drive around £50. Other than the cd drive that needs replacing the decks are in v good condition Can deliver if near enough. £300 ovvno. These decks are £250 - £300 new so grab a.



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>




2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>



2 x numark ndx 900 cd decks
 (1 faulty) plus 1 Numark IM09
 mixer.

<https://www.freeadsz.co.uk/x-253187-z>