

SKODA FABIA INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR



Location South East, West Sussex https://www.freeadsz.co.uk/x-296347-z



SKODA FABIA INSTRUMENT CLUSTER REPAIR (1999-2007)

£99

The Skoda Fabia Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers which involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required.. Your mileage reading will also stay intact, so there is no need for mileage correction.

Your Skoda Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one. COMMON ISSUES

Failing warning lightsSkoda Speedometer problemsFlickering clusterComplete power failurePixels failing on screen

REPAIR PROCEDURE

	CLUSTER CLOCKS
€ € lephor	https://www.fr 47-z
rite he ir	SKODA FA
	47-z oune dig offe
teferen tile box call vou	SKODn arc
	24 hour
e box to the ive	47-z ith aw.fr
s of th dure t tr Deli repair	SKODAY WARABA INST
ns on t Sic and S Sate Have	CLOCK y), to sup ille (ng
n tite Iasei al Via er an	47-z App erlog
tode o karess a Roya e clust	
Cipei Intera Distanta Ved to	KNAR CST rranty shop
ing yee 1, cut e 2nd sate /e recei	ND ⁷ I ime Wa our worl
move the book and p all through a the winn had book hen we ha	ARUSTER BOOK STRUMENT
	WAR 27-z We c Ifayou
	SKODA FABIA INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR
	https://www.freeadsz.co.uk/x-2963 47-z
	SKODA FABIA INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR
	https://www.freeadsz.co.uk/x-2963 47-z
	SKODA FABIA INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR
	https://www.freeadsz.co.uk/x-2963 47-z
	SKODA FABIA INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR
	https://www.freeadsz.co.uk/x-2963 47-z

CONTACT US

CARTRONIX

CALL: 02392 265 986 or 02392 241412 ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterlooville, PO7 7HT WEBSITE: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT PROGRAMMING!!! WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.