

# Back Door - Timber with double glazed window

Location **South East, West Sussex**  
<https://www.freedasz.co.uk/x-354552-z>



Timber construction back door with large double glazed window. Lower plywood panel requires replacing and small damaged area on one side, otherwise in sound condition with no rot. Hinges on RHS viewed from outside, door hinges inwards. Overall Size 1983H x 763W x 45t. Window size 990H x 580W (mm). Painted.



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>



Back Door - Timber with double glazed window

<https://www.freedasz.co.uk/x-3545>