FFOOACSZauk

Vango Aspen 700DLX Tent (125 GBP)



Location https://www.freeadsz.co.uk/x-517942-z

North, Cheshire



Vango Aspen 700DLX Tent

This is a Massive 7 birth tent. This was put up a couple of days ago to take the pictures. It was nice weather when it was put up & when it was packed away.

3 Bedrooms - 2 / 3 /2 or remove divide & have a 5 & 2, it also has a hanging rail. Huge living area & additional big porch area which has separate ground sheet. The main living area has a fully sewn in around sheet.

Mainly steel pole construction ,so a good solid sturdy tent.

Comes in 2 bags, Pole bag (which is heavy) & the Tent bag

It is in used condition so does have a few marks on it : Picture 8 is of the roof section of the inner tent. It is a rust mark where something was wrapped up inside of the inner tent & has marked it. This was on it when we got it. It might clean off with a cleaner, I don't know? Picture 9 is a small hole near 1 of the vents on the outer tent. There are colour matched pieces of genuine vango repair material with it so it's easy enough to cut a piece & glue it on, we just never bothered as this was also like it when we got it. Picture 10 is on the outer tent where 1 of the poles slides through it. A piece of the colour matched repair material could be glued onto this, once again this was like it when we got it. Picture 11 is what I would assume may well be some very small ember burns. Again this was like it when we got it and could easily be covered with some small bits of the colour matched repair material, we just never bothered. I can't be any more open & honest than that. As far as I know this is all that is wrong with it and it's easy to put right. This tent gets great reviews on the Ukcampsite website This is an absolutely massive tent, it's just to big for us since our eldest doesn't come camping with us any more.

